

Example of a Successful Application Industrial Roller Systems

Industrial plants using ROLLERS can frequently experience ongoing problems with SLIPPAGE that can and does cause Un-Scheduled Shutdowns, Loss of Production and High Maintenance Costs.

One example of this are Industrial Plants which use COAL.

The Unique Polymer Systems Distributor in Poland has recently carried out a coating application on a roller. The problem was SLIPPAGE.



This picture shows the roller after having surface preparation prior to the coating application. Angle Grinding took place whilst in situ.



THISTLEBOND TR 205 Fluid Ceramic was applied along with SiCa particles (#24) included in the WET application.



The THISTLEBOND CERAMIC range can offer protection in a vast number of applications.