

ThistleBond

www.thistlebond.info

EXAMPLE OF A SUCCESSFUL ENGINEERING APPLICATION

Cooling fins on transformer suffering from extreme corrosion



The Problem

Cooling fins on transformer suffering from extreme corrosion. Transformer is located by coastal region so there is also an element of SALT WATER corrosion.

The Solution



All surface were prepared manually and all excess material removed to leave a substrate suitable for repair with Thistlebond Engineering Polymers.

All badly corroded areas were repaired using **Thistlebond TR19065 Rapid Metal Repair** product. The whole area was then coated with **TR105** to cover over the repaired holes.

Contact: sales@thistlebond.info
www.thistlebond.info