



www.thistlebond.info

Advanced Polymer Solutions

Cargo Hold Repair and Protective Coating

ThistleBond Hycote 152 SFE & 152 SFE AS.



The Cargo Hold to the left had been used to carry powders over a period of time. The solids in the product had worn through the original protective coating and had started to attack the bare metal underneath. ThistleBond was approached to provide a coating system that would repair and protect the steel sides of the hold.

The Cargo hold was Hydroblasted and then cleaned using ThistleBond Universal Cleaners. The product chosen to protect the Cargo Hold was ThistleBond Hycote 152 SFE and SFE AS. All seams and sharp edges were coated with coat of Hycote 152 SFE (Brush Applied), then one coat of Hycote 152 SFE AS (Airless Spray) was applied over the top. Due to the high film thickness of the coating this was a one coat application, ThistleBond gave a 5 year warranty on the work..

