




[www.thistlebond.info](http://www.thistlebond.info)

**Coating of a Chemical Tank Hold**  
**Location: Canada**



Due to the corrosive nature of the materials being carried by the vessel, the original coating had been eaten away and the steel surfaces had become badly affected. ThistleBond put forward a system that would ensure that the chemical tank would be protected for the next 10 years. Once the cracks and pitting had been filled in, the entire surface of the tanks was Hydroblasted. This was to give the product chosen ThistleBond Hycote 175 Chemical Protection a good surface to bond too.



The ThistleBond Hycote 175 Chemical Protection was then roller applied to the steel surface. This two coat application was given a warranty for 10 years. The Hycote 175 is the ultimate in chemical protection and can withstand some of the most corrosive chemicals, such as Sulphuric Acid at 50% concentration at high temperatures.