



[www.thistlebond.info](http://www.thistlebond.info)

## Case History – ThistleBond Hycote 152 SFE Marine Deck Coatings



The German Ferry shown to the left had bad corrosion on the roof.

ThistleBond was asked to provide a solution for this particular problem and was given the contract to perform all the application work.

The Deck was blast cleaned to SA 2.5 50 micron profile and then degreased using ThistleBond Universal Cleaner



After the surface was prepared 2 coats of ThistleBond Hycote 152 SFE were applied.

This product had some Bauxite crystals mixed with it to give an anti slip surface to the Marine Deck.

The work was carried out 3 years ago and the Ferry is still in service today.