



www.thistlebond.info

Case History – ThistleBond Hycote 152 LV Marine Deck Coatings



The bottom of the steel hull had not been cleaned or anti fouled for over 6 years.

After taking the boat out of the water it was badly corroded and the rust had worked itself as far as 14mm into the steel bottom.

The steel hull was blast cleaned and degreased using ThistleBond Universal Cleaner.

All pitting and scarring was filled using ThistleBond TR105 Super Metal. This solvent free epoxy paste is ideal for heavy duty applications and can be easily machined down to a smooth finish



After the ThistleBond Super Metal had gone touch dry, a coat of Hycote 152LV was applied to all the steel surface.

A further 3 coats were applied.

The ThistleBond Hycote 152 LV is provided in variety of colours and on this particular project Light Grey and Dark Grey were used.

The boat has been in use for over 4 years and has had no problems with the rebuild and coating protection that was done by ThistleBond